

The function "Record" doesn't return when no trigger signals are available

mvAcquireControl

This problem has been fixed in version 3.105.3 of the mvAcquireControl and the SDK. From now on an image becomes available after the snap- or trigger timeout has elapsed even if no trigger pulse has been detected.