

## **No/black images with activated processing functions under the mvAcquireControl**

LabView, mvAcquireControl, mvIMPACT Go!, mvIMPACT S, mvIMPACT SDK, Halcon

This problem has been fixed since version 3.105 of the mvAcquireControl